



Blankettnr: BL10050
Utfärdad av: FN
Datum: 050114
Utgåva: 2

Z-LYFTEN PRODUKTION AB

Service Message

2019-01-21

Regarding: Voltage peaks disturb the operating of the tail lift.



Note! Applies tail lifts and vehicles with 12V system.

It has come to our knowledge that some customers have problems with that the lift stops during operation and will return running after releasing the button and press button again and it works a short while before it stops again.

If this behavior is only present when the vehicle is running and not if you turn of the vehicle then it is probably due to the fact that the vehicle produced a voltage peak when the vehicle was running.

The tail lifts electric system turns off at high voltage peaks as a protection for its electronics.

If the tail lift behaves as described above: Turn off the vehicle; If the lift then goes normally then the problem is that the vehicle has delivered voltage peaks to the lift.

If you have this problem please contact us.

email: zeproservice@hiab.com

tel: +46 10-4590503

*Note that previously sent out service messages are available at our website and in the C-files.
www.zepro.com, www.c-office.com*

Best Regards,
Zepro Z-Lyften Produktion AB

Christer Mattsson