

Ryder/Dominos suggested location stocking parts list for Gen 2 Rack and Pinion drive units.

Contact Waltco Part Department at 800-411-5685 for pricing

Part #	Description of part	Quantity per liftgate	Notes
91265923	Primary toggle switch control harness	1	Up / down switch asm 22'
91265924	Primary toggle switch control harness	1	In / out switch 22'
75089808	Multi-position toggle switch	6	Used in all interior mounted switch locations
27865200	Drive shaft bearing assembly	1	
27866000ZN	Drive axle assembly-Rack & Pinion drive Gen 2	1	
7500110-1	Hose, 1/4 X 19.0" 3/8 JICF X 1/4 SAE 0-	4	Pump to lift cylinder
7500109-1	Hose, 1/4 X 15.50 LG 3/8 JICF X 3/8 JICF	2	Pump to hydraulic motor
91318980	Hose, 1/4 X 15.50 LG 1/4 JICF X 3/8 JICF	1	Pump to hydraulic motor (replaced by 7500109-2)
27865200	Drive axle bearing assembly	1	Recommended when replacing drive axle
75088067	1/2" washer for drive axle bearing	1	
27821285	UHMW shim and stops	4	
27821290	UHMW stops	4	
27866535	Wheel assembly	8	Single wheel assembly 8 included with kit below
80004736	Kit, 2 piece Axles with wheels and bearings	1	one kit has 4 sets of axles and 8 wheels with bearings
91318945	Kit, Gen 2 (Rack & Pinion) Serviceable rail end kit	1	Needed if mandated refurb had not been done
	Motor can be used in primary or secondary position		
27869050	12V DC primary/secondary liftgate motor	2	
			total for all items per location

**For cost of complete replacement power unit, contact Waltco Parts
800-411-5685. Please have liftgate serial number available**

